Release Notes:
****
Version: Vigor3300B+ V2.5.7.4 Release

[New features]
1. Add user can change User-Agent Name Function.
   This function can let user change User-Agent Name at V3300V,
   default value is "Draytek V3300V-1.0.0".

[Fixed issues]
1.Fix ddos issue, router have low throughput when attacked by flooding, even enable ddos syn flood.
2.Enable multiple wan and 802.1q vlan, router cannot reset by web page.
3.Fix WAN DHCP issue, fail to get ip from Netgear WGR614v5 Cable router.
4.Fix p2p blocking fail using Foxy.
5.Fix pppoe fixed ip issue in UK, reject our fixed ip and give a dynamic one.
6.Fix static route bug, when router under 3300 lan using 2nd subnet, the host under the router cannot
  reach 3300'w WAN.
7.Fix p2p blocking fail using MSN 8.1 in Vista.
8.Fix ddns issue, fail to update IP for China ISP redirect advertisement page.
9.Fix using pppoa line with vigor100 bug.
10.Fix nat loopback issue, client under lan but not 3300's lan subnet(using static route to another
   router under 3300's lan) cannot access server under 3300 using port redirection.
11.Fix port redirection issue, set a rule to a host, the source port of the host be changed through nat.
12.Vigor 3300V NAT address mapping bug for PPPoE mode.
****