Release Notes:
\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*
\*\*\*\*\*\*\*\*\*\*\*\*
Version: Vigor3300V V2.5.7.4 RC2/Release
1.[#5810] Vigor 3300V NAT address mapping bug for PPPoE mode.
2.Fix SIP use intercall while Network failed issue
   Fix SIP can not use intercall while SIP using outbound proxy to make call.


\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*
\*\*\*\*\*\*\*\*\*\*\*\*
Version: Vigor3300V V2.5.7.4 RC1
[New features]
1. Add Bypass(Normal Mode) FAX mode.(#4456)
   The original "Bypass fax mode" change to Bypass Proprietary FAX mode.
   This mode only for 2 V3300V using.
2. Add user can change User-Agent Name Function.
   This function can let user change User-Agent Name at V3300V,
   default value is "Draytek V3300V-1.0.0".
3. Add Call without Registration Function.(#3213)
   It will not sent REGISTER request while "Call without Registration" is set in per port setting.
4. Modify response for SIP NOTIFY.(#3373)
   Modify response with 200 OK when receive SIP NOTIFY .
5. Modify Porland CallerID.(#3233)
   Modify Porland CallerID Type DTMF to ETSI.
6. Add line reversal on both mode.(#4548)
   It can do Line Reversal both callee on hook and callee answer mode.
7. Add Call Waiting feature.


[Fixed issues]
1.Fix ddos issue, router have low throughput when attacked by flooding, even enable ddos syn flood.
   (Reported from FAE Frank)
2.Enable multiple wan and 802.1q vlan, router cannot reset by web page. (#4239)
3.Fix WAN DHCP issue, fail to get ip from Netgear WGR614v5 Cable router. (Reported from FAE Sophia)
4.Fix p2p blocking fail using Foxy. (Reported from FAE Gareth)
5.Fix pppoe fixed ip issue in UK, reject our fixed ip and give a dynamic one. (#4831)
6.Fix static route bug, when router under 3300 lan using 2nd subnet, the host under the router cannot
  reach 3300'w WAN. (#4893)
7.Fix p2p blocking fail using MSN 8.1 in Vista. (Reported from FAE Gareth)
8.Fix ddns issue, fail to update IP for China ISP redirect advertisement page. (Reported from FAE Frank)
9.Fix using pppoa line with vigor100 bug. (#5206)
10.Fix nat loopback issue, client under lan but not 3300's lan subnet(using static route to another
   router under 3300's lan) cannot access server under 3300 using port redirection.
   (Reported from FAE Gareth)
11.Fix port redirection issue, set a rule to a host, the source port of the host be changed through nat.
   (Reported from FAE Kevin)
12.Fix ipsec crash, dial from host to lan client more than 12 using vpn tool SSH Sentinel.
   (Ticket#: 2007053010000448)
13.SIP use intercall while Network failed.
    When Network failed, SIP using extra speed dial to make call instead of
    using Proxy Server.